

Photographs for

(1) Four Black and white exterior photographs
North, South, East, West.

Four Black and white interior photographs

(2) photos of Other Buildings (Cottage 2)
(Garage 2)

(3) Views of The general setting are also
required view below Tucker street (1)
view above Fuller Street (1)

(4) North Arrow ↗

(5) A ~~sketch~~ map of location of Property
USGS or County Map is preferred

(6) Note Street and Route Numbers

(7) Cupola (1) Small Beams with mortise and
Tenon joints, wooden pegs
instead of Nails

(8.) Material of House - Flemish bond Pattern, Brick
arches over Basement Windows (See Page 4 Blandome)

Photographs for

(1) Four Black and white exterior photographs
North, South, East, West.
Four Black and white interior photographs

(2) Photos of other buildings (Contexts)
(General)

(3) Views of the general setting are also
required
view below Tucker Street (1)
view above Fuller Street (1)

(A) North Arrow

(2) A ~~map~~ map of location of property
USGS or County map is preferred

(3) Note street and route numbers

(7) Cupola (1)
Small beams with mortise and
tenon joints, wooden feet
instead of nails

(8) Material of floor - Flemish bond pattern brick
arches over basement windows (see part 4)